CIA-RDP78T05929A001300130003-0

31 January 1966

Page 8

## DUAL HEN HOUSE FACILITY ANGARSK, USSR

1. SIGNIFICANCE:

LARGE SCALE KH-7 REVEALS GREATER DETAIL FOR SUBSEQUENT TECHNICAL ANALYSIS.

2. REMARKS:

A TOTAL OF 10 DUAL HEN HOUSE FACILITIES AND 1
SINGLE HEN HOUSE HAS BEEN IDENTIFIED IN THE USSR
TO DATE. THE 4 DUAL HEN HOUSE FACILITIES AT
BOTH SITE 13 OF THE SARY-SHAGAN ANTIMISSILE
TEST CENTER AND ANGARSK ARE ORIENTATED GENERALLY
EAST/WEST AND ARE BELIEVED TO BE FOR SATELLITE
DETECTION AND TRACKING. THE DUAL HEN HOUSE FACILITIES AT BOTH OLENEGORSK AND SKRUNDA ARE ORIENTATED GENERALLY NORTHWEST AND ARE BELIEVED TO
HAVE A PRIMARY BALLISTIC MISSILE EARLY WARNING
FUNCTION. THE SINGLE HEN HOUSE AT SARY-SHAGAN
ANTIMISSILE TEST CENTER IS CONSIDERED THE R&D
MODEL.

3. LOCATION:

32 NM NW OF ANGARSK.

4. COLLATERAL/COMINT:

NONE

These notes have been prepared for briefing purposes only and should not be used for detailed analytical work. Their use should be restricted to the particular briefing board(s) they were prepared for and must be considered valid only for the reporting period as indicated by the date of issue.

31 January 1966

Page 9

FIRST IDENTIFICATION: 5.

6. NEGATION DATE:

SUBSEQUENT COVERAGE: 7.

ELEVEN KH-4 MISSIONS AND TWO KH-7 MISSIONS FROM FEB 64 THROUGH OCT 65 HAVE REVEALED 4 AREAS (DESIGNATED "A", "B", "C", AND "D"), EACH CON-TAINING A DUAL HEN HOUSE FACILITY.

8. DIMENSIONS SPECIFICATIONS:

HEN HOUSE: APPROXIMATELY 900 X 100 FT.

CENTRAL CONTROL BUILDING: APPROXIMATELY 240 X

200 FT.

TERMINAL BUILDING: APPROXIMATELY 75 X 35 FT.

9. MISSION READOUT: THIS MISSION REVEALS NO SIGNIFICANT CHANGE AT OPERA-TIONS AREA "B" OR "C", THE OPERATIONS SUPPORT, OR THE 3 SUPPORT AREAS

THE FACES OF THE ANTENNA BUILDINGS AT OPERATIONS AREA "A" ARE VISIBLE AND FOR THE FIRST TIME SHOW 43 BLACK PANELS ENCLOSING THE FRONT OF THE NORTH ANTENNA BUILDING AND 41 BLACK AND 2 GRAY PANELS ON THE FACE OF THE SOUTH ANTENNA BUILDING. THE NORTH ANTENNA BUILDING AND THE CENTRAL CONTROL BUILDING APPEAR TO BE EXTERNALLY COMPLETE WHILE THE SOUTH ANTENNA BUILDING APPEARS EXTERNALLY COMPLETE EXCEPT FOR THE LACK OF 2 BLACK PANELS ON THE SOUTH END OF THE STRUCTURE.

These notes have been prepared for briefing purposes only and should not be used for detailed analytical work. Their use should be restricted to the particular briefing board(s) they were prepared for and must be considered valid only for the reporting period as indicated by the date of issue.

2

31 January 1966

Page 10

WITH THE EXCEPTION OF THE CONNECTING STRUCTURES, THE CENTRAL CONTROL BUILDING AT OPERATIONS AREA "D" IS EXTERNALLY COMPLETE. THE CONNECTING STRUCTURES ARE PRESENT BUT HAVE NO ROOF AND ARE COMPLETELY OPEN FROM THE TOP. THE NORTHEAST TERMINAL BUILDING NEEDS ROOFING FOR FINALIZATION. THE NE ANTENNA FACE IS NOT VISIBLE AND THE PRESENCE OF PANELS CANNOT BE DETERMINED. THE SOUTHWEST LINEAR STRUCTURE IS STILL UNDER CONSTRUCTION AND IS APPROXIMATELY 60 PER CENT COMPLETE. ROOFING AND BLACK FACING PANELS HAVE BEEN INSTALLED ON STEEL TRUSSES AND COVER OVER HALF THE DISTANCE FROM THE CONTROL BUILDING SOUTHWESTWARD TO THE TERMINAL BUILDING. STEEL TRUSSES, WITH NO COVERING, ARE EMPLACED ALONG THE REMAINING DISTANCE FROM THE END OF THE ROOFING TO THE TERMINAL BUILDING, WHICH IS UNDER CONSTRUCTION AND IS APPROXIMATELY 90 PER CENT COMPLETE.

These notes have been prepared for briefing purposes only and should not be used for detailed analytical work. Their use should be restricted to the particular briefing board(s) they were prepared for and must be considered valid only for the reporting period as indicated by the date of issue.









